

Chevrolet Silverado

Below is a list of flaws and imperfections that are above and beyond normal wear and tear of this machine

<u>Item#</u>	<u>Description</u>
1	The plastic strip that attaches to the bottom front of the truck is missing. This item is about \$60-\$80 (guess) and it very common for this item to be torn off in the snow. This can be seen in picture #16
2	When the vehicle was new, it had mud flaps. The mud flaps have been removed as a result of snow, ice, and mud. This can be seen in side pictures of the vehicle.
3	The plastic panels underneath the engine and transmission have broke over the past five years due to snow and ice.
4	The drivers side seat and armrest on the center counsel are damaged from getting in and out of the vehicle. This can be seen in picture #15
5	Something hit the vehicle by the passenger door window and scratched the paint. This happened in 2015 but was bot bad enough to fix. It is a surface scratch. This can be seen in picture #14
6	The starter is showing wear. It might need to be rebuilt within the next year.